Fig.1a.









Fig.1b.

















Applied Rotation Rate - Degrees/sec.

0.06

0.08


0.04

0.02-

-0.04-


-90.0-

-0.08-



Quadrature Scalefactor - Arbitrary Units

Phase Correction - Degrees



Temperature - Degrees C